

The drawing consists of two parts. The upper part is a cross-sectional view of a mechanical assembly. It features a central vertical shaft (2) passing through a housing. A component (4) is mounted on the shaft. To the left, a gear-like component (10) is visible, connected to a shaft (6). Other labeled parts include 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, and 33. The lower part is a top-down view of a circular component (1). It has a central circular opening (16) surrounded by a ring (17). The ring has several small circular features (18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33) spaced around its circumference. A central vertical shaft (2) passes through the center of the ring. The shaft has a component (4) mounted on it. The shaft is connected to a component (10) which is part of a larger assembly (11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33).






FIG 3




FIG 4




FIG. 5

